
CHAÎNE DE MONTAGE CÂBLES HAUTE TENSION



LIGNE BERI.HV

Avec la chaîne de montage be-ri, l'assemblage des câbles haute tension avant le montage ultérieur des connecteurs est simple, rapide et souple.

La chaîne de montage est assemblée selon les exigences et les spécifications du client. Toutes les machines et tous les appareils peuvent être rapidement adaptés au câble correspondant.

La chaîne ci-dessus est conçue pour traiter un Câble HT 35 mm^2.

Les machines utilisées sont :

AM.ALL.ROUND 2Clamp
BERI.CO.CUT
BERI.CO.CLEAN
BERI.WRAP.UP
BERI.CLEAR.FRAME

Les étapes suivantes sont effectuées avec la chaîne ci-dessus (de gauche à droite) :

- dénudage de l'enveloppe extérieure
- raccourcissement de tresse
- nettoyage de la chaîne
- écartement et retournement de la tresse (via l'anneau de support)
- dénudage du conducteur intérieur (bande partielle)




Toutes les machines mentionnées dans l'exemple ci-dessus sont fixées sur nos nouvelles tables de montage BERI.CLEAR.FRAME. Le système de tables permet une organisation du travail propre avec une élimination systématique des déchets ainsi qu'un positionnement ergonomique de toutes les machines et appareils.

FEINTECHNIK
R.RITTMEYER GMBH
Höltenweg 103
48 155 Münster
Germany

Telefon: +49 . (0)251.96115–0
Telefax: +49 . (0)251.624 525
E-mail: info@rittmeyer-beri.de
Web: www.rittmeyer-beri.de

Assembly Line High Voltage Cables



BERI.HV.LINE

With the be-ri high-voltage assembly line, the assembly of high-voltage cables before subsequent connector assembly is simple, fast and flexible.

The line is assembled according to requirements and customer specifications. All machines and devices can be quickly converted to the respective cable.

The line shown above is designed for processing a 35 mm^2 HV cable.

The used machines:

AM.ALL.ROUND 2Clamp
BERI.CO.CUT
BERI.CO.CLEAN
BERI.WRAP.UP
BERI.CLEAR.FRAME

The following steps are performed with the above line (from left to right):

- stripping the outer jacket
- braid shortening
- cleaning the line
- spreading and turning of the braid (via the support ring)
- stripping the inner conductor (partial strip)



All machines in the above example are mounted on our new assembly tables BERI.CLEAR.FRAME. The table system allows clean working with orderly waste disposal as well as ergonomic positioning of all machines and devices.