
# Linia Montażowa Kabli Wysokiego Napięcia




## BERI.HV.LINE

Zastosowanie linii montażowej be-ri umożliwia proste, szybkie i sprawne przygotowanie kabli wysokiego napięcia do montażu złączy i konektorów.

Montaż linii następuje zgodnie ze specyfikacją i wymogami klienta. Każdą z maszyn i urządzeń wchodzących w jej skład można szybko przezbroić pod konkretny rodzaj kabla.

Zaprezentowana powyżej linia jest dostosowana do obróbki kabli wysokiego napięcia o przekroju 35mm2

Następujące etapy pracy są wykonywane za pomocą przedstawionej powyżej linii montażowej (od lewej do prawej):

- Ściąganie izolacji zewnętrznej
- Skracanie oplotu
- Oczyszczanie linii
- Rozkładanie i wywijanie oplotu (poprzez pierścień oporowy)
- Ściąganie izolacji przewodu wewnętrznego (częściowe)

Zastosowane podzespoły:

AM.ALL.ROUND 2Clamp
BERI.CO.CUT
BERI.CO.CLEAN
BERI.WRAP.UP
BERI.CLEAR.FRAME




Wszystkie podzespoły użyte w powyższym przykładzie mocowane są na naszych nowych stołach montażowych BERI.CLEAR.FRAME. Nasz system stołów zapewnia czyste warunki pracy poprzez zorganizowany system utylizacji odpadów oraz ergonomiczne rozmieszczenie wszystkich maszyn i urządzeń.

**FEINTECHNIK**
**R.Rittmeyer GmbH**
Höltenweg 103
48 155 Münster
Germany

Telefon: +49 . (0)251.96115–0
Telefax: +49 . (0)251.624 525
E-mail: info@rittmeyer-beri.de
Web: www.rittmeyer-beri.de

# Assembly Line High Voltage Cables




## BERI.HV.LINE

With the be-ri high-voltage assembly line, the assembly of high-voltage cables before subsequent connector assembly is simple, fast and flexible.

The line is assembled according to requirements and customer specifications. All machines and devices can be quickly converted to the respective cable.

The line shown above is designed for processing a 35 $mm^2$ HV cable.

The used machines:

AM.ALL.ROUND 2Clamp
BERI.CO.CUT
BERI.CO.CLEAN
BERI.WRAP.UP
BERI.CLEAR.FRAME

The following steps are performed with the above line (from left to right):

- stripping the outer jacket
- braid shortening
- cleaning the line
- spreading and turning of the braid (via the support ring)
- stripping the inner conductor (partial strip)



All machines in the above example are mounted on our new assembly tables BERI.CLEAR.FRAME. The table system allows clean working with orderly waste disposal as well as ergonomic positioning of all machines and devices.